



TECH TIPS

Dixie Part Numbers: S-1414 S-1515

Applications: 2006 – 2009 Buick Lucerne

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- the check engine indicator lamp is on
- the engine fails to start or crank
- the back light for the gear selector window has stopped functioning.

The technician may observe one or more of the following diagnostic trouble codes stored in the system:

P0712 P0713 P0716 P0717 P0748

Cause: A potential cause for the above conditions is the transmission wiring harness may be misrouted and pulled taught against the transmission case, the transmission cable support bracket or both.

Correction: Inspect the transmission wiring harness for chaffing and damage, repair the damaged wired (if any) and re-route the transmission wiring harness away from the transmission and the shift cable support bracket, if required, following the manufacturer's recommended procedures.