



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Buick LaCrosse
2010 Cadillac SRX

Condition: The operator of the vehicle may complain of hard starting, no starting or frequent dead battery occurrences.

Cause: A potential cause for the above condition is a software flaw in the keyless entry system which prevents other modules from going into the sleep mode, thereby creating excessive parasitic or quiescent draw.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures to update the required calibration files.