



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Chevrolet Express Van – G Series Van
2010 GMC Savana – G Series Van

Condition: The operator of the vehicle may complain of one or more of the following intermittent conditions:

- A low or dead battery
- A no crank, no start situation

Cause: A potential cause for the above is an internal short in the accessory wiring junction block.

Correction: With everything off, there should be very little voltage drawn by the accessories, measure the voltage and if the reading is above 10V the accessory wiring junction may require replacing. Follow the manufacturers recommended replacement procedures when required.

