



TECH TIPS

Dixie Part Numbers: A-1759 A-80212 A-80214 A-80221
 A-9503 S-6263 S-6276 S-6281
 S-6282 S-6558

Applications: 2007 Audi A6 (VIN 000001 – 073265)
 2007 Audi A8 (VIN 000001 – 010103)
 2007 Audi Q7 (VIN 000001 – 063347)

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- The battery is low or discharged.
- The engine fails to crank or start

Cause: A potential cause for the above condition is a software malfunction that prevents the radio receiver from entering the sleep mode.

Correction: The manufacturer has released a software update to address this issue. Follow the manufacturer's recommended procedures for verifying and updating the software, when applicable.