



TECH TIPS

Dixie Part Numbers:	S-1424	S-1468	S-1490	S-1497
	S-1498	S-1499	S-1511	S-1515
	S-1518	S-1522	S-1523	S-1525
	S-8997	S-80060	S-80280	S-80334
	S-80335	S-80390	TBA	

Applications:

- 2006 – 2011 Buick Lucerne
- 2006 – 2011 Cadillac DTS
- 2006 – 2007 Chevrolet Monte Carlo
- 2006 – 2012 Chevrolet Impala
- 2007 – 2009 Pontiac Torrent
- 2007 – 2009 Saturn Outlook
- 2007 – 2012 Cadillac Escalade
- 2007 – 2012 Cadillac Escalade ESV
- 2007 – 2012 Cadillac Escalade EXT
- 2007 – 2012 Cadillac SRX
- 2007 – 2012 Chevrolet Avalanche
- 2007 – 2012 Chevrolet Equinox
- 2007 – 2012 Chevrolet Silverado
- 2007 – 2012 Chevrolet Suburban
- 2007 – 2012 Chevrolet Tahoe
- 2007 – 2012 GMC Acadia
- 2007 – 2012 GMC Sierra
- 2007 – 2012 GMC Yukon
- 2007 – 2012 GMC Yukon XL
- 2008 – 2009 Hummer H2
- 2008 – 2012 Buick Enclave
- 2008 – 2012 Cadillac CTS
- 2008 – 2012 Chevrolet Express (G Series Van)
- 2008 – 2012 GMC Savana (G Series Van)
- 2008 – 2010 Saturn Vue

Condition: The technician may observe diagnostic trouble code P0633 retained in the engine control module after the engine fails to start. The *Tech 2* cannot clear the diagnostic trouble code.

Cause: A potential cause for the above conditions is a flaw in the engine control module. Code P0633 is not a “fault” code it is an indicator that the engine control module has been triggered to enter the learn mode. Any malfunction that causes the engine to fail to start will prevent the diagnostic trouble code from being cleared.

Correction: Diagnose and repair the cause of the engine not starting and start the engine. Once the engine successfully starts the engine control module will clear the P0633 code from the memory.

REV: 20120416 – Expanded years range to include 2012 models

REV: 20120416

Courtesy of APRA

TSB_195.docx

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.