



TECH TIPS

Dixie Part Numbers: S-2095, S-2098, S-80143

Applications: 2001 – 2002 Ford F150 and SuperDuty F Series with either the alternate fuel or liquid propane fuel options.

Condition:

The vehicle may exhibit some or all of the following conditions:

- cranking with out starting when operating in alternate fuel mode (the alternate fuel light will be on) and when in gas mode the vehicle operates
- surging when idling and/or surging when at the cruise condition (the alternate fuel light will be on).
- repeat starter motor failures.

Cause:

The potential cause for this could be the following:

- a contaminated Compuvalve,
- contaminated or faulty Low Flow Injectors,
- a faulty Compuvalve system board,
- or contaminated fuel that has caused the Low Flow Injectors to stick.

Correction:

Follow the manufactures procedures for testing the Compuvalve system