



TECH TIPS

Dixie Part Numbers: S-2136

Applications: 2003 – 2004 Ford Focus 2.3L PZEV Engine

Condition: Some vehicle operators may complain of long or hard cranking and when performing tests the malfunction indicator lamp does not come on and there are no diagnostic trouble codes present.

Cause: The cause may be an out of date calibration file.

Correction: Ensure that the calibration file on the PCM (excluding PCM 12650D and 12650D84) are B39.7 or higher.