



TECH TIPS

Dixie Part Numbers: S-6267, S-6268, S-6560

Applications: 2006 Audi A3 (BPY engine code) up to VIN 8E_6A073016
2006 Volkswagen Golf "GTI" (BPY engine code)
2006 Volkswagen Jetta (BPY engine code)

Condition: Some vehicle operators may complain of one or both of the following conditions:

- The engine does not crank intermittently.
- Nothing happens when trying to start the engine.

The engine does start if the ignition sequence is repeated.

The technician will not find any diagnostic codes in the system memory.

Cause: A possible cause for the above conditions is out-of-date software installed in the vehicles ECM.

Correction: Follow the manufacturer's recommended procedures for verify and updating the ECM program.