



TECH TIPS

Dixie Part Numbers: S-6263 S-6558

Applications: 2005 Audi A6 all vehicles
2006 Audi A6 vehicles with VIN numbers 000001 - 037400

Condition: The operator of the vehicle may have one or more of the following conditions:

- the engine will not start
- the ignition cannot be turned on
- the ignition key cannot be removed

Cause: The cause for the above condition has been traced to the Access/Start Control Unit being damaged internally from the transient voltage created by the starter motor.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures which include ensuring that the Access/Start Control Unit wire connections are in good condition, and that the voltage supply and ground are not compromised. They also recommend removing the black/red lead from position 19 of the 20 pin connector on the Access/Start Control Unit and taping it back into the harness. If damaged, the Access/Start Control Unit will require replacement.