



TECH TIPS

Dixie Part Numbers:	A-766	A-778	A-788	A-792
	A-795	A-796	A-1697	A-1698
	A-1700	A-1701	A-1702	A-1704
	A-6498	A-7001	A-7002	A-7007
	S-8814	S-80234	TS-1758	TS-1767
	101-24101	101-24104	101-24107	101-24201
	160-55110	201-29103	201-38101	246-30115

Applications: 2005 – 2006 Thomas Built Buses

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- the vehicle fails to start
- the vehicle has caught on fire
- the battery is run down/dead

Cause: A potential cause for the above conditions is the main battery cable chaffing on a bracket next to the starter resulting in a short circuit to ground.

Correction: When working on a vehicle from the above applications inspect the main battery cable. Replace and re-route the battery cable if applicable.