



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 Chrysler Sebring
2009 Dodge Avenger
2009 Dodge Caliber
2009 Dodge Journey
2009 Jeep Compass
2009 Jeep Patriot

In all applications the manufacturing date range is from July 10, 2008 to August 26, 2008 (MDH 071011 to 082606).

Condition: The operator of the vehicle may complain that the engine has stalled and fails to restart.

Cause: The above vehicles were subject to a recall pertaining to the potential for the power train control module failing due to the circuit board being suspect of fracturing. The power train control module was manufactured incorrectly with an adhesive that could cause the circuit board to fracture.

Correction: Verify that the power train control module has been replaced and the calibration files updated with the current revision.