



TECH TIPS

Dixie Part Numbers: S-80145 206-07126 and TBA

Applications: 2006 Ski-Doo MX Z Adrenaline
2006 Ski-Doo MX Z Trail
2006 Ski-Doo MX Z Renegade X
2006 Ski-Doo GSX Sport
2006 Ski-Doo GTX Sport
2006 Ski-Doo GTX Ltd
2008 Polaris 550 LX
2008 Polaris Trail Touring
2008 Polaris Trail Touring Deluxe

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- a grinding noise while starting
- complete failure of the flywheel/ring gear

Cause: The manufacturers of the above applications have noted several failures pertaining to cracks in the ring gear.

Correction: Inspect and replace the flywheel if required. In all applications (when inspecting and replacing the flywheel) torque the flywheel mounting bolts to the manufactures specifications.