



TECH TIPS

Dixie Part Numbers: A-8981 A-80222 A-80234 S-80032
 S-80295 S-80305 S-80307 S-80308
 S-80327 S-80343 S-80379

NOTE: Not all applications assigned Dixie numbers at this time

Applications:

2006 – Infiniti Q45
2006 – 2007 Infiniti G35 Coupe
2006 – 2008 Infiniti G35 Sedan
2006 – 2009 Infiniti FX
2006 – 2009 Infiniti M
2008 – Infiniti EX35
2008 – 2009 Infiniti G37 Coupe
2009 – Infiniti G37 Sedan

Condition:

The operator of the vehicle may complain that the malfunction indicator lamp is illuminated, particularly if the battery has been low, dead or disconnected (such as when doing any electrical work on the vehicle). The technician will observe that diagnostic trouble code P0603 is stored in the electronic control module.

Cause:

The electronic control module will report code P0603 any time that the voltage goes below a predetermined amount and stay in the system until reset.

Correction:

Depending on the cause take appropriate action, the code may have been triggered by such events as starting the engine in extreme cold or after leaving the vehicle parked with out starting for an extended period. Additionally the code will be triggered if there is a problem in the charging system (such as poor wiring or a faulty battery). After performing an evaluation of the condition of the charging system reset the electronic control module following the manufacturer's recommended procedures.