



TECH TIPS

Dixie Part Numbers:	A-80306	A-80307	A-80338	A-80344
	A-80347	A-80352	A-80353	A-80354
	A-80383	S-8730	S-8772	S-8976
	S-80072	S-80384	S-80401	TBA

Applications: 2006 – 2008 Toyota Rav4 with the remote engine start option
2007 – 2010 Toyota Camry with the remote engine start option
2007 – 2010 Toyota Tundra with the remote engine start option

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- A low or dead battery
- Long, slow cranking cycles
- Hard starting.

Cause: A potential cause for the above conditions is a flaw in the remote starter module that results in an above normal parasitic drain.

Correction: The manufacturer has released an updated remote engine starter module to correct the parasitic drain issue. Follow the manufacturer’s recommended repair procedures to diagnose and replace the module if applicable. The originally installed module was part number 08190-42830, the replacement one is PT398-42080.