



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 – 2011 Mazda RX8

Condition: The operator of the vehicle may complain of difficulty starting after running the engine for a short period without the engine heating up to normal operating temperatures.

Cause: There are 2 potential causes for the above condition:

- The spark plugs are soaked in fuel preventing the engine from starting (the engine is "flooded").
- There is lower than required compression for the engine to start; this could be due to the seals sticking from carbon deposits.

Correction: Follow the manufacturers recommended diagnostic and repair procedures when applicable.

Rev: 20110502 Initial Release
20121109 Updated model year range