



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2011 Chrysler Town & Country
2011 Dodge Durango
2011 Dodge Grand Caravan
2011 Dodge Nitro
2011 Dodge Ram Pickup (1500, 2500, 3500)
2011 Dodge Regular Cab Chassis
2011 Jeep Cherokee
2011 Jeep Grand Cherokee
2011 Jeep Liberty
2011 Jeep Wrangler

Conditions: The operator of the vehicle may complain that intermittently the vehicle alarm sounds for no reason and that the vehicle requires numerous attempts before starting. The technician will find diagnostic trouble codes U0001 and U0010 stored in the system

Cause: A potential cause for the above conditions is an error in the totally integrated power module (TIPM) programming logic.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable which include clearing the codes and updating the software.