



TECH TIPS

Dixie Part Numbers: A-8898

Applications: 2001 – 2002 Acura MDX

Condition:
The charging system and brake light indicators simultaneously flicker on and off while driving.

Cause:
Electrical noise generated by the cooling fan circuit causes the warning lights to flicker. This does not affect the performance of the braking system.

Correction:
Use a Dixie replacement alternator, which has the updated components, incorporated into it to filter out the electrical noise.