



TECH TIPS

Dixie Part Numbers: A-80032 and S-80319

Applications: 2007 Acura MDX VIN 2HNYD28--7H500001 to 2HNYD28--7H523800

Condition: The operator of the vehicle may complain of a low or dead battery, the charge warning light coming on, hard starting and/or not starting.

Cause: A possible cause is a sticking power door lock switch on either the driver or passenger's side resulting in a low or dead battery. The switch will stick if it is not aligned properly (resulting in a 3A draw).

Correction: Align the power lock switches, replacing the brackets if required, following the manufacturer's recommended procedures.

REV: 20100308 A-80337 removed (superceded) A-80032 added.