



TECH TIPS

Dixie Part Numbers: A-80244 A-80334

Applications: 2006 – 2007 Chrysler PT Cruiser built before January 22, 2007 (MDH0122XX)

Condition: The operator of the vehicle may complain that the charge-warning lamp (Generator Lamp) may come on intermittently. The technician may observe diagnostic trouble code P063A stored in the system.

Cause: A potential cause for this is the factory installed calibration file.

Correction: Before checking any of the charging system components verify that the factory installed calibration file on the Powertrain Control Module has been updated. This will be noted on an Authorized Modification decal near the Vehicle Emission Control Information decal referencing TSB 18-007-07. If the calibration file has not been updated this should be done following the manufacturer's recommended procedures.