



TECH TIPS

Dixie Part Numbers: A-80013 A-80014 A-80015 A-80016
 S-8751 S-8977 S-80045

Applications: 2001 – 2003 Dodge Durango (with bench seat)

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- the vehicle battery is dead
- the engine fails to crank
- the vehicle caught on fire

Cause: The above conditions may be due to an unused power console power outlet connector (used on the bucket seat model) which was mounted under the cup holder...perhaps as a beverage warmer. It has been found, however, that when beverages spill they typically form a conductor and may result in the above condition.

Correction: The manufacturer has made a cap to prevent additional contamination and short circuits. Follow the manufacture's recommended procedures when installing the cap.