




P.T.O. SWITCH	
ON	A+B
OFF	C+D, B+E

KEY SWITCH	
OFF	M+G
RUN	B+L
START	B+S