



TECH TIPS

Dixie Part Numbers: S-2099 S-2124 S-8423

Applications: 2000 – 2003 Ford Econoline E Series 7.3L Diesel
2000 – 2003 Ford Excursion 7.3L Diesel
2000 – 2003 Ford F Series Pickup 7.3L Diesel
2003 – 2004 Ford Excursion 6.0L Diesel
2003 – 2004 Ford F Series Pickup 6.0L Diesel

Condition: The operator of the vehicle may complain of hard starting or a no start condition on vehicles equipped with the glow plug control module. The technician may not observe any diagnostic trouble codes in the system.

Cause: A potential cause for the above condition has been identified by the manufacturer as the plug in connectors for the glow plug control module.

Correction: Follow the manufacturer's recommended procedures for inspecting the black and green glow plug control module plug in connections for corrosion, bent pins and for a tight fit. If any of the conditions exist kit 4CZ-12B568-AA may be required to repair the connectors.