



TECH TIPS

Dixie Part Numbers: A-8300 S-6154

Applications: 1996 Dodge Neon
1996 Plymouth Neon

Condition: The operator of the vehicle may complain of various electrical problems including:

- Stalling and/or failure to start
- Erratic charging

Cause: A potential cause for the above condition is that the engine wiring harness was routed in close proximity to the exhaust gas recirculation tube and over time may chaff and short circuit to ground.

Correction: The manufacturer recommends inspecting and repairing the wiring and re-routing the wiring harness away from the gas recirculation tube, when applicable.