



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 Nissan Cube with Intelligent Key option

Conditions: The operator of the vehicle may complain that the engine fails to start.

Cause: The vehicle is equipped with an electronic steering column lock, as a theft deterrent. Some of the electronic steering column locks were manufactured with irregularities which could cause them to malfunction and prevent the vehicle from starting.

Correction: Follow the manufacturer's recommended inspection, diagnostic and repair procedures when necessary.