



TECH TIPS

Dixie Part Numbers: S-8462

Applications: 2002 – 2004 Isuzu Axiom

Condition:

Customers may have a concern that the starter continues to crank up to 20 seconds after the key is released if the engine does not start.

Cause:

The system is programmed with a “convenient starting operation” and will crank the engine up to 20 seconds even if the key is released. The starter will not crank and will cease the “convenient starting operation” if turned to the off position.

Correction:

This is a design feature of the vehicle and is not a flaw.